



SCA#2 Ash Landfill –looking southeasterly

January 14, 2021



SCA#2 Ash Landfill – west face looking southerly  
Lift #1, #2 and #3 covered and seeded. Lift #4 in process

January 14, 2021



Surface of Lift #4 in process – photo looking northwesterly January 14, 2021  
Compaction appears satisfactory. Dust suppression appears satisfactory



Surface of Lift #4 in process – photo looking south-southeast January 14, 2021



South Perimeter Ditch – looking easterly

January 14, 2021



Sediment Pond 018, located west of Sed Trap #1 – photo looking westerly  
Pond has water with a surface ice layer and recent snow cover.  
No discharge in 2020  
Sediment Trap #1 is empty and clean, water flows from trap to pond in normal open condition.

January 14, 2021