



SCA#2 Ash Landfill –looking southeasterly

January 2, 2019



SCA#2 Ash Landfill – west face looking southerly  
Lift #1 and #2 covered and seeded, vegetation is growing. Lift #3 in process

January 2, 2019



Surface of Lift #3 in process – photo looking northwesterly

January 2, 2019



Sediment Pond 018, located west of Sed Trap #1 – photo looking westerly

January 2, 2019

Recent storms with ice reducing the evaporation and pond appears nearly full of water.

No discharge in 2018

Sediment Trap #1 is empty and clean, water flows from trap to pond in normal open condition.