



SCA#2 Ash Landfill –looking southeasterly

January 18, 2023



SCA#2 Ash Landfill – Current surface northwesterly
Lift #4 in progress

January 18, 2023



SURFACE OF LIFT 4 - IN PROGRESS

Surface of Lift #4 in process – photo looking east - southeast

January 18, 2023



SURFACE OF LIFT 4 - IN PROGRESS


Surface of Lift #4 in progress – photo looking west - southwest
Compaction appears satisfactory. Dust suppression appears satisfactory
Surface slopes east towards the hill to prevent storm water run-on

January 18, 2023



Sediment Trap #1 is empty and clean
water flows from trap to pond 018 in normal open condition.

January 18, 2023



Sediment Pond 018, located west of Sed Trap #1 – photo looking southwesterly
Pond has water with a surface ice layer and recent snow cover.
No discharge in 2022

January 18, 2023