



SCA#2 Ash Landfill –looking southeasterly

January 3, 2020



SCA#2 Ash Landfill – west face looking southerly
Lift #1 and #2 covered and seeded. Lift #3 in process

January 3, 2020



Surface of Lift #3 in process – photo looking northwesterly

January 3, 2020



Sediment Pond 018, located west of Sed Trap #1 – photo looking westerly

January 3, 2020

Pond has water with a surface ice layer and recent snow cover.

No discharge in 2019

Sediment Trap #1 is empty and clean, water flows from trap to pond in normal open condition.